

TEST	PERFORMANCE LEVEL				
	1	2	3	4	5
Wear resistance (turns)	100	500	2,000	8,000	
Cut resistance (factor)	1.2	2.5	5	10	20
Tear resistance (newtons)	10	25	50	75	
Puncture resistance (newtons)	20	60	100	150	

TEST	PERFORMANCE LEVEL					
	A	B	C	D	E	F
TDM: Cut resistance (newtons)	2	5	10	15	22	30