




















Selection of protective clothing

	MICROGARD						MICROCHEM						L.BRADOR					
	1500	2000 COMFORT		2000 PLUS			3000			4000			DC 20			DC 30		
	 	 		  			  			  			  			  		
Production, preparation and handling of chemicals							3, 4, 5			3, 4, 5								
Paint stripping, hazardous							3, 4, 5			3, 4, 5								
Paint spraying (with isocyanate) see 0.005 ppm							3, 4, 5			3, 4, 5								
Paint spraying (not isocyanate)				4, 5, 6														
Chemical decontamination							3, 4, 5			3, 4, 5								
Low-risk chemical protection				4, 5, 6														
Spraying with pesticides				4, 5, 6			3, 4, 5			3, 4, 5								
Oil-based dirt protection							3, 4, 5			3, 4, 5								
Asbestos removal	5, 6																	
Food processing		5, 6		4, 5, 6														
Laying insulation	5, 6	5, 6		4, 5, 6									5, 6			4, 5, 6		
Wood and metal treatment	5, 6	5, 6		4, 5, 6									5, 6			4, 5, 6		
Resin application				4, 5, 6												4, 5, 6		
Light spraying with cleaning fluids	5, 6	5, 6		4, 5, 6									5, 6			4, 5, 6		
Medical first aid				4, 5, 6			3, 4, 5			3, 4, 5								
Radioactive dust		5, 6		4, 5, 6			3, 4, 5			3, 4, 5								
Steam and water pressure cleaning				4, 5, 6												4, 5, 6		
Cleaning tanks containing hazardous liquids							3, 4, 5			3, 4, 5								